

Certificate

Standard **ISO 9001:2015**

Certificate Registr. No. 0.04.23001 MS

Certificate Holder: **ULMA MANUTENCION, S.COOP.**
Barrio Garagaltza, 50
20560 Oñati (Gipuzkoa)
España.

Scope: Engineering and installations of Logistics Solutions for internal handling of products and goods. Provision of associated technical assistance and after-sales services. Manufacturing of logistics solutions for internal handling of products and goods.

Proof has been furnished by means of an audit that the requirements of ISO 9001:2015 are met.

Validez: The certificate is valid from 2023-09-01 until 2026-08-31.
First certification 2023.

2023-09-20



TÜV Rheinland Ibérica Inspection,
Certification & Testing S.A.
Garrotxa, 10-12 – E-08820 El Prat de
Llobregat



Annex to certificate

Standard **ISO 9001:2015**

Certificate Registr. No. **0.04.23001 MS**

No.	Location	Scope
/02	ULMA MANUTENCION, S.COOP. Barrio Garagaltza, 50 20560 Oñati (Guipuzkoa) Spain.	Engineering and installation of Logistics Solutions for internal handling of products and goods. Provision of associated technical assistance and after-sales services.
/03	ULMA MANUTENCION, S.COOP. Otxandio: Bº Zelaieta s/n 48210 Otxandio (Bizkaia) Spain.	Manufacturing of logistics solutions for internal handling of products and goods.

2023-09-20



TÜV Rheinland Ibérica Inspection,
Certification & Testing S.A.
Garrotxa, 10-12 – E-08820 El Prat de
Llobregat